


SLOW DOWN WHEN TURNING



Travel slowly when turning*. Forklift can tip over even at very low speeds.

The combination of speed and the sharpness can cause a tipover